

Sensor	Repairable Product	Inspection Fee	Repair Price	Calibration
LevelSCOUT	No	N/A	N/A	\$140
BaroSCOUT	No	N/A	N/A	\$140
PT2X	Yes	\$250	\$605	\$140
PT2X-BV	Yes	\$250	\$440	\$140
PT12	Yes	\$250	\$440	\$140
PT12-BV	Yes	\$250	\$330	\$140
PS9800	Yes	\$250	\$410	\$140
PS9800 w/ temp	Yes	\$250	\$495	\$195
PS98i	Yes	\$250	\$330	\$140
CT2X	Yes	\$250	\$825	NA
CT2X w/ Level	Yes	\$250	\$990	\$195
TempHion pH	Yes	\$250	\$990	\$550
TempHion ISE	Yes	\$250	\$990	\$550
Turbo	Yes	\$250	\$1,980	\$195
DO2	Yes	\$250	\$1,980	NA
Multiparameter	Yes	\$250	Quoted	Quoted
Set-screw style housing, all models	Yes	\$250	Quoted	Quoted

Guidelines

- Above pricing is for stainless. Add \$55 for titanium units
- TempHion calibration includes replating
- Products returned within the warranty period and are within 2 years of the product's initial release, will be inspected at no charge for cause of failure. If failure is found to be from misuse or misapplication, and not covered by the warranty, an inspection fee will be charged. • Warranty freight: Seametrics pays both ways. If no problem is found, customer will be responsible for return freight
- Non-warranty freight: Customer pays both ways. PO Needs to be issued at the time the RMA is set up for non-warranty work
- **Products must be cleaned before return. Products not cleaned will be assessed a minimum \$100 cleaning fee. Cleaning applies to products involving dirt, slurries or other non-hazardous material or fluids. Products involving hazardous, or unknown fluids, must also include an SDS. For employee safety, products involving hazardous or unknown material or fluids, and not cleaned or accompanied by an SDS, will be returned**
- If customer decides to rebuild the product, after the inspection, the inspection cost will be credited to the rebuild
- If customer decides to buy new, after the inspection, the inspection cost will be credited to the new sensor purchase
- Batteries are considered a maintenance item and not under warranty
- **All of the above prices are net to Seametrics**
- **Products will be returned after 10 business days of inspection, if we do not get a response on how to proceed. Inspection fee will still be charged**